# **WARDE HAZCON**

lert
A
ent
id
lnc
nt
Ca
hifi
igr
S

Type of Incident	Damage/Production Loss Ground Engaging Tool & steel pipes ending up in Crusher.		
Key Issues			
INX Incident No	59044		
Date & Time	Saturday, May 15, 0500 hrs		
Location	Crusher		
Injury	None		

### DESCRIPTION

A drill pipe measuring about 1.5 meters long was dumped with ore by the mining haul trucks and got caught inside the CV41/CV43 transfer chute. This resulted in ripping about half the length of the conveyor belt and caused the crusher to be U/S for two days.



# LESSONS

- Comply to existing plans for removal of metals from mining areas.
- Maintain vigilance over known risk areas where metal may be a hazard

# ACTIONS

- Reinforce existing GET and metal recovery process into the 24hr plan.
- Visible daily 24-hour plot to include all metal and GET data
- Manage metal infested mining blocks as per current process
- Identify all possible risk with metal sources
- Improve communication between the mine and crushing teams in regards to reporting steel trip events at the Crusher.

### David Kwong

Acting Manager – Mine Technical Services

Department::	Status:	Issued:	Page 1 of 1
Mining	Approved	06/06/21	Business Confidential