

Type of Incident Equipment Damage, HiPo Near Miss

Key Issues Situational Awareness

INX Incident No ID 66465

Date & Time Sunday, July 25th 2021, 1110pm


Location Taranaki 1, T junction

Injury None

DESCRIPTION

A Toyota Land cruiser 5 door (L1943), driven by the night shift supervisor and carrying one passenger had stopped to give way for a Caterpillar 793F haul truck HT213 and a Caterpillar 789C haul truck HT106 to pass.

Caterpillar 793F HT206 was on its way towards OK Ningi ROM to access HX06 when it slowed down to give way at the T junction behind the light vehicle, it came too close





- Always be aware of your work surroundings and what goes on around you.
- Comply to critical system controls they are there for a reason.

ACTIONS

- Review T junctions and where practicable include segregation of LV and Haul trucks.
- Safe Mine Collision avoidance refreshers to be rolled out.
- Review and inspect LV buggy whip lights.

Fergus Hart

Manager

Department::	Status:	Issued:	Page 1 of 1
Mining	Approved	15/08/21	Business Confidential

OHS Standard 4-03 Form - HAZCOM	MGR OHSWT	09/03/2017	1.0	09/03/2017	09/03/2019	1 of 1