

Type of Incident Laceration to head – Injury.

Key Issues Lack of situational awareness

INX Incident No 104053

Date & Time Saturday, 12 November 2022, 07:40Hrs

Location Geneva Deepcore Workshop

Injury Head Injury.

DESCRIPTION

LV Fitter was conducting daily prestart on Canter Truck. IP started the engine and heard unusual noise. IP opened the door, came out of the truck, crouched to check where the sound was coming from. After checking and attempting to stand upright, IP's head made contact with the truck door that was left open resulting in head laceration.

LESSONS

- Always wear proper PPEs during activities that could cause injury or injury to other body parts.
- All routine jobs must be developed into SWP and all steps and use of tools to be captured in the procedure.
- Hazard Identification and risk awareness to be communicated consistently during pre-start meetings.

ACTIONS

- Stand down Meeting with the maintenance team
- Full PPE to be worn within DC Workshop area and Mandatory PPE signs to be erected within the Workshop area.
- Address DC team on complacency
- Create SWPs for all routine jobs at the workshop, including vehicle Pre-start checks.

Rarua OALA

Manager – Geology & Exploration

Department:	Status:	Issued:	Page 1 of 1
Geology & Exploration	Approved	26/12/2022	Business Confidential